

PIER POWER PROCEDURE

1. To energize the AC receptacles on the piers, turn on breakers 5 and 7 in the right-hand breaker panel located behind the bifold doors in the hallway leading to the dome.
2. To illuminate the pier LED's and energize the 12 Volt DC plugs inside the pier boxes, turn on the ASTRON 12 Volt power supply located in the basement equipment bay.